Outgoing Quality Assurance Flow Chart

Version: 2.0

OQA Process

Department	Process
Operations	Manufacturing
Operations	Inner Packing
OQC	Sampling
OQC	Test → N → Rescreen /Sorting
Logistics	Labeling (Y)
Logistics	Outgoing Packaging
Logistics	Data Entry
	The End

Test → N → Rescreen/Sorting → N → Manufacturing
Test → Y → Labeling
Rescreen/Sorting → Y → Labeling